



FCGS 9969

North

Bearings based on the east line of Section 10 as being S 04°05'32"W between FCGS Monuments 9869 and 9819.

Ind M. Harrison et al  
Instrument Number 199709110091932

N 85°45'00"W 1292.05'

3/4" Iron Pipe Found

S 04°03'07"W 157.00'

529.94'

3/4" Iron Pipe Found

John and Jill Caylor  
Instrument Number 19980909229373

S 85°45'00"E 1408.89'

5.0196 Acres

N 85°35'59"W 1409.73'

Daniel L. Shannon et al  
Instrument Number 199903240073240

3/4" Iron Pipe Found

3/4" Iron Pipe Found

William S. and  
Sandra L. Carter  
Official Record 1153403

3/4" Iron Pipe Found

3/4" Iron Pipe Found

3/4" Iron Pipe Found

N 04°21'36"E

Northeast Quarter Section 10  
Northwest Quarter Section 10

Richardson Road

5.0196 Acre Parcel

Section 10, Township 10 North, Range 21 West  
of the Buckingham Survey of the Congress Lands  
Madison Township, Franklin County, Ohio

Plat Book


Scale: 1" = 200'

Date: November 5, 1999

Drawn By: RGR

Ahlers, Moe & Associates, Inc.

Engineering & Surveying  
360 West Waterloo St. P.O. Box 2  
Canal Winchester, Ohio 43110  
(614) 837-1178



Job No: 99-2520

0-50-B  
MADISON TWP.

06356600