

RECEIVED

Franklin County Engineer
Dean C. Ringle, P.E., P.S.

James L. Purdie
I.N. 199705290010305
18.000 Ac.

James R. McNabb
& Lynn M. McNabb
I.N. 200702080023830
6.504 Ac.

Heather Goodman
& Marina Barash
I.N. 200902170020895
5.01 Ac.

Joseph W. Anderson &
Mildred B. Anderson
O.R. 13254J09
44.095 Ac.

James L. Purdie
I.N. 199801220015341
71.000 Ac.



Orrin R. Thornton
& Patricia A. Thornton
O.R. 17346D06
5.0327 Ac.

- Iron Rod Found
- Iron Pipe Found
- ✕ PK Nail Found
- ▲ RR Spike Found
- Ⓜ Monument Box
- Iron Pin Set
- ✕ PK Nail Set
- △ RR Spike Set
- Ⓜ Monument

All iron pins set are 3/4" diameter, 30" long iron pipes with plastic cap inscribed "Advanced 7661".

Bearings are based on the Ohio State Plane Coordinate System per NAD83, South Zone (1986 Adj.). A bearing of S03° 55' 05"W was held between Franklin County Monuments FCGS 4443 and FRANK 181.

This drawing is based on existing records and an actual field survey performed in October 2009.



Quarter Township 1, Township 2, Range 16, U.S.M.D.
Township of Plain, Franklin County, Ohio

Boundary Survey and Split
for
David Goodman

ADVANCED CIVIL DESIGN ENGINEERS & SURVEYORS

422 Beecher Road
Gahanna, Ohio 43230
ph 614.428.7750
fax 614.428.7755

SCALE: 1" = 60'
DATE: 05/24/2010

SHEET 1 / 1

Z:\09-0002-346\survey_split_recover.dwg Layout1 May 26, 2010 3:11:07pm jcdodj