



Note: Bearings shown on Highway Easement No. 6 should be rotated 2° 56' 10" clockwise to conform to the bearings shown on this plat.

DETAIL 'A'  
Scale 1" = 40'

26.152 - 3/2/65  
- 2.000 - 5/21/65  
24.152  
2.317 - 8/2/65  
21.778

Plat prepared from two surveys made by Thomas Engineering & Surveying Co. dated July, 1960 and Jan. 1961 and deeds of exchange between the Post Office Dept. and Sears, Roebuck & Co. dated April 23, 1964. Monuments and Iron Piles shown were found May 7, 1964.

**ALDEN E & ASSO**

PROPER  
SEARS, RO  
COLUMBUS