

HOY SURVEYING SERVICES, INC.

ORDER NO. _____

6040 CLEVELAND AVENUE

COLUMBUS, OHIO 43231

PHONE 614-895-1922

FAX 614-895-1949

CERTIFIED TO MAROLDA LOMES

COUNTY OF FRANKLIN

LENDER _____

P.B. 86 PG. 92 OR. _____ PG. _____

BUYER _____ DATE 10.28.98

SCALE 1" = 30' DRN JG CH S.V.H.

BLACKLICK ESTATES NO. 6

P.B. 37 PG. 42

1045

1045

N 07° 50' 30" E

2.00

32.0

57.96

10' EASE.

EX. 20' SAN. SEW. EASE. O.R.V. 2769 PG. 801

146.67

262

25

CLATTERTON SECTION 1 COLUMBUS, OHIO

N 82° 09' 30" W 180.62'

S 82° 09' 30" E 181.16'

0.0083 ACS.

20' SAN. SEW. EASE.

25' BLDG. LINE

POINT OF BEGINNING

52.32'

RETRIEVER ROAD 50'


ST. BERNARD CIRCLE 50'

2.07
N 22° 54' 28" E
R: 20' Δ: 5° 56' 10"

NOTE: ALL IRON PINS DENOTED ARE 3/4" I.D. x 30" HOLLOW IRON PIPE PLUGGED WITH A PLASTIC CAP BEARING THE NAME "HOY SURV. P.S. 7313"

We hereby certify that the foregoing BOUNDARY SURVEY was prepared in accordance with Chapter 4733-37, Ohio Administrative Code, pursuant to Chapter 119 of the Ohio Revised Code.

THE BEARING SYSTEM USED FOR THIS BOUNDARY SURVEY IS INTENDED TO CORRESPOND WITH THOSE SHOWN ON SAID RECORD PLAT OF CLATTERTON SECTION 1.

By  Registered Surveyor No. _____



86 856 950